



IND.A.G.O. s.n.c.

Indagini e Opere Ambientali e Geologiche

via Balzan, 1 - 45100 Rovigo - tel. 0425-25185


www.indago-rovigo.it

2D-3D Electrical tomography on a waste site

DESCRIPTION:

An electrical tomography survey, commissioned by Daneco Impiantri srl, was carried out on Sant'Arcangelo Trimonte – Benevento province (Southern Italy) - municipal waste; the aim of the survey was to check the presence of leachate below HDPE membrane. ERT profiles were useful to detect contaminated areas. Some 2D/3D inversions are reported below.

2d inverted section example:



3d view:

